



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3916-041
Job Sheet 194789



Part No: D3916-041

Job Qty: 6 pcs

Part Name: Rib Assembly



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 5/8/19

Job Tracking No:

Due Date: 6/26/19

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG REV A IPP RevA: New issue DD verified by:EC IPP Rev:B as per dwg revA 10.03.15 verified by:EC
Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Large Fab - Basket - 1	6 pcs	6/26/19		0.00	2.73	Large Fab - 1		
							Large Fab - 10		
							Large Fab - 2		
							Large Fab - 3		
							Large Fab - 4		
							Large Fab - 5		
							Large Fab - 6		
							Large Fab - 7		
							Large Fab - 8		
							Large Fab - 9		5.4
105	QC 5	6 pcs	6/26/19		0.00	0.00	QC 5 - 10		
							QC 5 - 12		
							QC 5 - 17		
							QC 5 - 18		
							QC 5 - 19		
							QC 5 - 22		
							QC 5 - 24		
							QC 5 - 3		
							QC 5 - 43		DAS 43 6-30
							QC 5 - 49		
107	Large Fab - Basket - 2 - B4B	6 pcs	6/26/19		0.00	3.43	QC 5 - 51		
							QC 5 - 58		
							QC 5 - 68		
							QC 5 - 9		
							QC 5 - 50		
	Large Fab - 1 - B4B						QC 5 - 30		
							QC 5 - 40		
							Large Fab - 10 - B4B		
							Large Fab - 2 - B4B		
	Large Fab - 3 - B4B						Large Fab - 3 - B4B		



Container No: S204375



Part: D3916-041

Job No: 194789

Serial No/Batch: S204375

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

Date: 08/09/19

Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Plex 5/8/19 1:45 PM Dart.lajeunesse.marie

					Large Fab - 4 - B4B	
					Large Fab - 5 - B4B	
					Large Fab - 6 - B4B	MAC
					Large Fab - 7 - B4B	
					Large Fab - 8 - B4B	
					Large Fab - 9 - B4B	
110 QC 5	6 pcs	6/26/19	0.00 0.00		QC 5 - 10	
					QC 5 - 12	
					QC 5 - 17	
					QC 5 - 18	
					QC 5 - 19	
					QC 5 - 22	
					QC 5 - 24	
					QC 5 - 3	DAS
					QC 5 - 43	43
					QC 5 - 49	9-89
					QC 5 - 51	
					QC 5 - 58	
					QC 5 - 68	
					QC 5 - 9	
					QC 5 - 50	
					QC 5 - 30	
					QC 5 - 40	
120 QC 10	6 pcs	6/26/19	0.00 0.00		QC 10 - 10	
					QC 10 - 18	
					QC 10 - 24	
					QC 10 - 43	DAS
					QC 10 - 50	43
					QC 10 - 58	9-89
					QC 10 - 9	
130 Packaging 3-1 - Stock - B4B	6 pcs	6/26/19	0.00 0.00		Packaging 3 - 1 - B4B	
					Packaging 3 - 2 - B4B	
					Packaging 3 - 3 - B4B	
					Packaging 3 - 4 - B4B	
					Packaging 3 - 5 - B4B	
					Packaging 3 - 6 - B4B	
					Packaging 3 - 7 - B4B	
					Packaging 3 - 8 - B4B	
					Packaging 3 - 9 - B4B	
					Packaging 3 - 10 - B4B	
					Packaging 3 - 11 - B4B	
					Packaging 3 - 12 - B4B	
					Packaging 3 - 13 - B4B	
					Packaging 3 - 14 - B4B	
					Packaging 3 - 15 - B4B	
					Packaging 3 - 16 - B4B	
					Packaging 3 - 17 - B4B	
					Packaging 3 - 18 - B4B	DAS
					Packaging 3 - 19 - B4B	43
					Packaging 3 - 20 - B4B	9-89
					Packaging 3 - 21 - B4B	
					Packaging 3 - 22 - B4B	
					Packaging 3 - 23 - B4B	
					Packaging 3 - 24 - B4B	
					Packaging 3 - 25 - B4B	
					Packaging 3 - 26 - B4B	
					Packaging 3 - 27 - B4B	
					Packaging 3 - 28 - B4B	
					Packaging 3 - 29 - B4B	

5/8/2019

[Dart Hawkesbury] Job Sheet - Lajeunesse, Marie

					Packaging 3 - 30 - B4B	
					Packaging 3 - 31 - B4B	
					Packaging 3 - 32 - B4B	
					Packaging 3 - 33 - B4B	
					Packaging 3 - 34 - B4B	
					Packaging 3 - 35 - B4B	
					Packaging 3 - 36 - B4B	
140	QC 21 - SA	6 pcs	6/26/19	0.00 0.00	QC 21 - SA - 21	DAS
					QC 21 - SA - 70	21
					QC 21 - SA - 53	9-35 AUG 13 2019

Part Op **100** - 1- Cut tube 50" 2- Bend tube with manuel pipe bender as per DT9567 *** Make line at 9.00" and use jig for other Descriptions: lines, and ensure seam in place on side of tube when bending*** 3- Trim access tube material to finish size as per dwg D3916 4- Drill and chamfer holes as per dwg D3916-1 using DT9605
105 - (QC5- Inspect part completeness to step on W/O)
107 - (Weld per dwg A/R S.S. rod Batch: M139015) 1- weld bushing as per dwg D3916 2- grind welds flush
110 - (QC5- Inspect part completeness to step on W/O)
120 - (QC10- Inspect visual per QSI004- ground welds)
130 - (Identify as per dwg & Stock Location: _____) LOCATION: WA004-5
140 - (QC21- Final Inspection - Work Order Release)

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D3759-1	Bushing	42 pcs (7 ea)	100-Large Fab - Basket - 1	S184002
M304TS0.750W.049	304 Sq Tube .75X.75X.049W	24.9960 ft (4.166 ea)	100-Large Fab - Basket - 1	S194042

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Large Fab - Basket - 1	D3759-1	42	75	0
	M304TS0.750W.049	25	255	0

Part Specifications

Specifications could not be found.

Plex 5/8/19 1:45 PM Dart.lajeunesse.marie

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QSI042)	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor	
				QC / QA Coordinator	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					